


The J20 is a 20-way (18+2) junction box complete with tamper.

INSTALLATION

To install, connect the TMP terminals to the panel tamper circuit.

Place links over the corresponding header blocks to join opposing sides of the circuit board. For example, placing a link over the pins marked 5 will join the wiring attached to 5A & 5B. See the diagram below for more information:



NOTES

Ensure wiring does not short other connections inside the unit

The tamper switch circuit is normally closed. Opening the lid will break the circuit.